KS-200A+ Rectification Explanation Document

Applicable Models: KS-200A+

Document Type: Instruction Manual

Version: V1.0

1. Rectification Background

1.1 Issue Overview

• We have identified certain deficiencies in the current product, where the AIS signals transmitted by the device fail to display the MMSI code when received by MarineTraffic base stations. These issues negatively impact user experience and require immediate corrective actions to ensure product quality and meet customer expectations.

2.Detailed Operating Steps

2.1 Preparation of Tools

Tools/Materials Preparation	Instructions		
Screwdriver			
Soldering Iron	Temperature:320~380°C		
Safety Goggles			

Tools Illustration Guide



Screwdriver


Soldering Iron



- 2. Implementation Steps for Modification
- 2.1 Remove the rear case screws using a screwdriver




2.2 Locate the KS-20A shielding metal case and remove the screws on both sides



2.3. Use a screwdriver to remove the screws on both the top

and bottom sides of the shielding metal cover.





Top Screws



Bottom Screws

2.4. Use a screwdriver to remove the internal plastic screws.


Note: The plastic screws are secured with adhesive and may be difficult to disassemble.



2.5. Flip the motherboard to the back side, use a soldering iron

to heat and remove resistor R26 to complete the modification.

(In special cases where a soldering iron is unavailable, diagonal cutters may be used to clip off the resistor. Avoid damaging other components during the operation.)



2.6 Place the motherboard back into the shielding metal casing, fasten the plastic screws, secure the shielding metal casing with screws, reinstall it into the main unit, and tighten the screws on the outer casing to complete the operation.



2.7 Test Results

After connecting the device to the antenna and waiting for a while, access the MarineTraffic website and search for the device's own MMSI code. If the device's own MMSI is found, the rectification is successful this time.

nci Urzani Kalahistin Mangsta Tanja Urzani Tanima Urzana Iriza Ira Isana Urza Ira Neger Venen Camero Ethogo Madres Madysta	View on live map Pacific Ocean	What kind of ship is th	is? 2552108) is a Fishing and	th China (reported 11 minut	
Tanzania	Bapua New Guinea Exafter I & Maptor & OpenStreetMap	Leafler / & Mapbox & OpenStreetMap General		Latest AIS information	
eparture from Lagos IG LOS	L. Unknown	Be the first to upload a photo for this		Navigational status	Class B
-	Be the first to upload a photo for this vessel			Position received	12 mins ago
Actual time of departure: 2025-01-04 15:58 (UTC+1)		Upload a photo		Vessel's local time	2025-03-25 19:37 (UTC+8)
		Name	ONWA 2108	Latitude/Longitude	Upgrade to unlock
Past track	Route forecast	Flag	China	Speed	0 kn
		IMO		Course	331 °
Locked cont	MMSI	412552108	True heading	331 *	
Upgrade your account to unlock this		Call sign	5	Rate of turn	
		AIS transponder class	Class B	Draught	
		General vessel type	Fishing	Reported destination	
		Detailed vessel type	Fishing		
		Service Status	Upgrade to unlock	Matched destination	(*)
At arrival location Near the vessel		Port of registry	Upgrade to unlock	Estimated time of arrival	
	lear the vessel	Vose built	Lloarade to unlock	AIS source	Terrestrial

3.Precautions

3.1Burn Prevention

• The soldering iron tip can reach temperatures exceeding 300°C—do

not touch. Keep it away from power cables during operation.

• Always place the soldering iron on a stand to prevent tipping.

3.2Ventilation

• Solder fumes contain lead and harmful gases (e.g., rosin vapors).

Operate in a well-ventilated area or use a fume extractor.

3.3Anti-Static Measures

• Wear an anti-static wrist strap to prevent electrostatic discharge (ESD)

damage to components.