To reinitialize the MSMS No for Camino 108, follow the steps below:

1. Execute the "AIS class B Configuration Utility" and connect it to your class B transponders. Click continuously on the "MMSI" for at least 3 seconds

Configuration		Diagnosis
TATIC DATA TRANSCEIVER BAUD	RATE	
ALLSIGN		
		(0~511m)
MMSI	- 04 M K	
hip Type 20 = Wig		

2. A pop-up window will appear. Input the activation code **2367** in the red marked area and then press "Active".

Register Lincese:	
Please contact distributor and provide yo process activation code for MMSI change	our configured MMSI to
Please enter the activation code.	Active

3. The MMSI No is reset and now you can configure the new MMSI No. After entering the new MMSI, click on "Config Device" to save the new setting.